



EXTERNAL MEASURES

PRECISION FORCE CALIPER FOR EXTERNAL MEASUREMENTS GIVES POSSIBILITY RECEIVE ACCURACY UP TO $\pm 0,010\text{MM}$.

1. ZERO SETTING

PUSH THE WHEEL UP TO 8N FORCE AND SET ZERO ON CALIPER



2. MEASURING PROCESS

MAKE MEASURING WITH 8N FORCE ON FORCE INDICATION



INTERNAL & DEPTH MEASURES

FOR INTERNAL & DEPTH MEASURING ACCURACY ACCORDING DIN STANDART $\pm 0,030\text{MM}$.

1. ZERO SETTING

WITHOUT FORCE MODULE



INTERNAL MEASURING LIKE IN USUAL CALIPER

(WITHOUT CALIBRATION WITH FORCE MODULE)



DEPTH MEASURING

LIKE IN USUAL CALIPER

(WITHOUT CALIBRATION WITH FORCE MODULE)

