

BIG SCREEN NIB CALIPER MICROTECH USER MANUAL



Calibration ISO 17025:2017

ISO 9001
BUREAU VERITAS
Certification




ISO 9001:2015



Item No	Range		Resolution		Accuracy	Jaw	Protection
	mm	inch	mm	inch	μm	mm	
141083321	0-300	0-12"	0,01	0.0004	± 30	60/40	IP54

BUTTONS





- Wipe with a clean cloth, soaked in gasoline, measuring surface of the frame and gauge calipers to remove anti-corrosion oil. Then wipe them with a clean dry cloth.
- If necessary, open the battery cover; insert the battery (type CR2032) according to the polarity of the electrodes. Blinking display information or absence suggests replacing battery.
- During the measurement, measuring jaws should to sum to the measured object without knocking.
- During the measurement avoid warps of measuring surfaces of the instrument. Measuring surface must be fully in contact with the measurement object.




WARNING!

IN THE PROCESS OF WORKING WITH CALIPERS SHOULD BE AVOIDED:

Scratches on the measuring surfaces;

Measuring the size of object in the process of machining;

Shocks or dropping, avoid bending of rod or other surfaces.



Range	DIMENSIONS				
	A	B	C	D	E
mm	mm	mm	mm	mm	mm
0-300	413	40	24	10	17

MICROTECH

innovative measuring instruments

61001, Kharkiv, Ukraine, str. Rustaveli, 39

tel.: +38 (057) 739-03-50

www.microtech.ua

tool@microtech.ua

Change without prior notice